



From:
Cooper Restorations
5304 S Adams
Marion, IN 46953
cooperrestorations@gmail.com

Invoice Number	CR-3076
Order Number	11313
Invoice Date	September 27, 2023
Total Due	\$0.00

Billing address	Shipping address
Donald Conner	Lloyds Auto Body
1265 Pearl St	3779 N US Highway 31
Austin, IN 47102	Seymour, IN 47274

Hrs/Qty	Service	Rate/Price	Sub Total
1	67-72 C10 rear bumper chrome (fleetside)	\$304.00	\$304.00
1	67-72 C10 rear bumper bracket set flt side or step side	\$65.00	\$65.00
1	rear bumper bolt kit	\$20.00	\$20.00
1	69-72 Chevrolet Tailgate band "CHEVROLET" (woodgrain)	\$230.00	\$230.00
1	71-72 MOULDINGS-LOWER BODY WITH WOODGRAIN ACCENT COMPLETE SET Longbed (Mar-K)	\$1,113.00	\$1,113.00
1	Tail light bezel 69-72 Chevy & GMC Fleetside LH	\$16.50	\$16.50
1	Tail Light Bezel Clip Kit 69-72 Chevy & GMC Pickup & Suburban	\$8.00	\$8.00
1	67-72 C10 back up lamp lens fleetside LH	\$6.75	\$6.75
1	67-72 C10 tail lamp lens red	\$9.00	\$9.00
1	67-72 C10 tailgate fleetside no lettering	\$303.75	\$303.75
1	68-72 C10 bedside FLT side 8' LH	\$742.50	\$742.50
1	67-72 C10 fleetside tailgate hardware kit 7pcs	\$114.75	\$114.75
1	67-72 Tailgate bumpers (set)	\$10.00	\$10.00

Subtotal:	\$2,943.25
Shipping:	\$398.50 via Shipping
Total:	\$3,341.75

Parts will ship after the invoice has been paid in full.